



CONSIGLI

Est. 1905

WINCHESTER HIGH SCHOOL – SCHEDULED WORK UPDATE

Week of 3/1/2015

- Removal of snow from site. (ongoing)
- Erection of structural steel bracing, trusses, and fly loft at Auditorium (Building D).
- Installation of new PVC roofing at Dining Commons (Building B).
 - Roofing adhesives can be odorous, however, are all within allowable VOC exposure limits.
- Spray fireproofing of Dining Commons structural steel. (ongoing)
- Installation of interior framing in Dining Commons, and 2nd floors of Building B Partial. (ongoing)
- Installation of overhead duct on 1st and 2nd floor of Building B Partial. (ongoing)
- Installation of HVAC rough-in in Dining Commons. (ongoing)
- Installation of overhead plumbing on 1st and 2nd floor of Building B Partial. (ongoing)
- Installation of plumbing rough-in and in Dining Commons and 2nd floor of Building B Partial. (ongoing)
- Installation of overhead electrical on 1st and 2nd floor of Building B Partial. (ongoing)
- Installation of electrical rough-in in Dining Commons, 1st, and 2nd floors of Building B Partial. (ongoing)
- Place concrete roof and slab at New Music Room.
- Place concrete roof at New Administration.
- Installation of roof blocking and curbs at New Administration and New Music Room.
- Installation of electrical rough-in in the crawl space. (ongoing)
- Installation of gas piping in the crawl space. (ongoing)
- MEP layout and hanger installation in new boiler room (Building E).