



# CONSIGLI

*Est. 1905*

## **WINCHESTER HIGH SCHOOL – SCHEDULED WORK UPDATE**

### **Week of 3/15/2015**

- Erection of structural steel bracing and fly loft at Auditorium (Building D).
- Installation of new PVC roofing at New Music Room and New Administration.
  - Roofing adhesives produce a strong odor. This is a LEED compliant material, and the VOC content is well below allowable limits.
- Spray fireproofing of New Music Room and New Administration structural steel.
- Installation of drywall on 2<sup>nd</sup> floor of Building B Partial. (ongoing)
- Installation of overhead duct on 1<sup>st</sup> and 2<sup>nd</sup> floor of Building B Partial. (ongoing)
- Installation of HVAC rough-in in New Music Room. (ongoing)
- Installation of overhead plumbing on 1<sup>st</sup> and 2<sup>nd</sup> floor of Building B Partial. (ongoing)
- Installation of plumbing rough-in and on 1<sup>st</sup> and 3<sup>rd</sup> floor of Building B Partial and in the New Music Room. (ongoing)
- Installation of overhead electrical on 1<sup>st</sup> and 2<sup>nd</sup> floor of Building B Partial. (ongoing)
- Installation of electrical rough-in in Dining Commons and 1<sup>st</sup> floor of Building B Partial. (ongoing)
- Installation of sprinkler rough-in on 2<sup>nd</sup> floor of Building B Partial. (ongoing)
- Installation of roof blocking at New Administration.
- Installation of electrical rough-in in the crawl space. (ongoing)
- Installation of gas piping in the crawl space. (ongoing)
- MEP layout and hanger installation in new boiler room (Building E). (ongoing)