



CONSIGLI

Est. 1905

WINCHESTER HIGH SCHOOL – SCHEDULED WORK UPDATE

Week of 3/22/2015

- Installation of drains and excavation in New Music Plaza.
- Erection of structural steel fly loft at Auditorium (Building D).
- Installation of new PVC roofing at New Administration and Auditorium.
 - Roofing adhesives produce a strong odor. This is a LEED compliant material, and the VOC content is well below allowable limits.
- Spray fireproofing of New Administration structural steel.
- Installation of CMU elevator shaft in Building B. (ongoing)
- Installation of Stair in Dining Commons.
- Framing walls on 3rd floor of Building B Partial.
- Installation of drywall on 1st and 2nd floors of Building B Partial. (ongoing)
- Installation of overhead duct on 3rd floor of Building B Partial. (ongoing)
- Installation of plumbing rough-in in Dining Commons and New Music Room. (ongoing)
- Installation of electrical rough-in in Dining Commons New Music Room. (ongoing)
- Installation of sprinkler rough-in in New Music Room. (ongoing)
- Installation of CMU at fly loft at Auditorium (Building D).
- Installation of steel stud framing at fly loft at Auditorium (Building D).
- Installation of electrical rough-in in the crawl space. (ongoing)
- Installation of plumbing rough-in in the crawl space. (ongoing)
- MEP layout and hanger installation in new boiler room (Building E). (ongoing)